	TE-PUFPLUS Hi-Vol Calibration Data Form
Site In	Cction
	e Name: Burns Harbor - Port of Indiana
Site Ab	obreviation BHP Sampler Serial No. 1006
Field T	breviation BHP Sampler Serial No. 1006 Cechnician Name Fate Haile & Fatie Healy Date 9/12/21 Time 11:56 CST
Timer	/Sensor Checks Allow Temp/Pressure standard to acclimate for 10 minutes before reading.
Is the	date correct? (YES) NO (circle one) time within +5 minutes of local standard time? (YES) NO (circle one)
	Delta Cal DCI
	Temp/Pressure Standard Got date
Temp	/Pressure Standard Serial No.: Transfer Standard - Transfer Standa
	this 12°C of the Transfer Standard? [1E3] NO (Child and
Is the	PUFPLUS Temperature sensor within ±2 Col the Transfer Standard (Pamb transfer standard - Pamb PUFPLUS) = mmHg ransfer standard (mmHg) 43.0 Pamb PUFPLUS (mmHg) 44.0 (Pamb transfer standard - Pamb PUFPLUS) = mmHg
P _{amb t}	ransfer standard (mmHg) Pamb PUFPLUS (mmHg) (mmHg) (circle one)
Is the	PUFPLUS Pressure sensor within ±10mmHg of the Transfer Standard? (ES) NO (circle one) both of the above are YES, sensor check is complete. Proceed with flow check.
• If	both of the above are YES, sensor check is complete. Proceed with how check. By the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check.
● If	either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry also calibration was done here: calibration point to the faulty sensor as described in the SOP in Section 10.2.3. Note that a calibration was done here:
C-15	bration Orifice Information
Can	Wales (Model: Grasely / Tisch Orifice Serial No.: 6212
Oriti	ce Make/Model: Graseby / TiSch Orifice Serial No.: 62K ice Slope "morifice": 10.46067 Orifice Intercept "borifice": -0.16706
Orif	ice Slope "morifice":
Orif	ice Certification Date: 2/4/21
Hi-	Vol Calibration Information Check off each item.
► F	ow Conditions are set to "STD"?
∀ F	low Rate is set to 225 liters per minute?
C	alibration Method: Manual Automatic (circle one) nter m _{orifice} value from above when prompted to "Enter Calibrator Standard m".
E	nter m _{orifice} value from above when prompted to "Enter Calibrator Standard b". Inter b _{orifice} value from above when prompted to "Enter Calibrator Standard b".
F	inter b _{orifice} value from above when prompted to Bitter data.
M	Hi Flow Rate should be 247 liters/min
AI	Correction Coefficient "R" 0.9994 >0.990? Yes No (circle one)
(Correction Coefficient "R" 0.9997 Ves No (Circle One) Hi-Vol Intercept "bhivol" (A0) -1.3193
]]	Hi-Vol Slope "mhivol" (A1) 35.2933 Hi-Vol Intercept "bhivol" (A0)
	lote: If the Correction Coefficient is ≤0.990, repeat the calibration.
M	Calibration saved?